

RUST




Table IV, Defect No. 109, Major defect. Pitted rust developed in retort basket.