

## OUTSIDE TINPLATE OR COATING (WHEN REQUIRED)



Table IV, Defect No. 203, Minor defect. Enamel missing - flaked.