

DENT




Table IV, Defect No. 110 - Major defect. Severe end seam dent. End seam forced out of position to such an extent that the counter sink (channel next to end seam) has been buckled materially affecting, or is likely to materially affect, the usability of the container.